

APPENDIX 2: FACILITIES TRANSITION PLAN



Accessibility Ranking

Rating	Description
0	Existing lot is signed and striped appropriately with adequate number of spaces. Some locations are at service yards where parking is not signed but also not an issue. No timeline required.
1	High priority project, often in a high use area. Accessible spaces may not exist or may be present with incorrect signage and striping. These projects are usually an easy fix. Recommend year 1 to 2 implementation.
2	Priority project, often in a high use area. Accessible spaces may not exist or may be present with incorrect signage and striping. Additional spaces may be needed. Recommend year 3 to 4 implementation.
3	Medium priority project, often in a medium use area. Accessible spaces may not exist or may be present with incorrect signage and striping. Additional spaces may be needed. Recommend year 5 to 6 implementation.
4	Low priority project, often in a low use area. Accessible spaces may not exist or may be present but located in the wrong location. Project often requires a little more work because there is nothing present at this time. Recommend year 7 to 8 implementation.
5	Extremely low priority project, often in a low use area. Accessible spaces are often not present and not needed. These are often in little used parking lots, sometimes aggregate lots. Recommend year 9 to 10 implementation.

PRIORITY 1. PRIMARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Total Spaces	Total # of HC Spaces	# that are Van Accessible	Required HC Spaces	Required Van Spaces	Space Meet All Requirements	Notes	Cost	Timeline	Priority Ranking
Delhi	Skips Canoe Livery	38	2	0	2	1	Yes	Appears to meet all requirements	456	Completed 2019	0
Delhi	East Delhi - North Lot	75	6	1	3	1	Yes	Appears to meet all requirements	456	Completed 2019	0
Dexter-Huron	Southeast Lot	45	2	1	2	1	Yes	Appears to meet all requirements	893	Completed 2019	0
Dexter-Huron	Northwest Lot	32	2	1	2	1	Yes	Appears to meet all requirements	893	Completed 2019	0
Dexter-Huron	Northeast Lot	42	2	1	2	1	Yes	Appears to meet all requirements	893	Completed 2019	0
Hudson Mills	Activity Center West	306	8	2	8	2	Yes	Appear to meet all standards. Old striping is showing through.	1,248	Completed 2019	0
Hudson Mills	Activity Center East							Parking lot totals have been grouped with the west lot.	1,248	Completed 2019	0
Hudson Mills	River Grove	94	4	2	4	1	Yes	Appears to meet all requirements	1,248	Completed 2019	0
Hudson Mills	Golf Course	128	5	1	5	1	Yes	Appears to meet all requirements	1,248	Completed 2019	0
Hudson Mills	Pine View	70	3	1	3	1	Yes	Appears to meet all requirements	1,248	Completed 2019	0
Huron Meadows	Acorn Ridge	53	5	1	3	1	Yes	Appears to meet all standards	1,192	Completed 2019	0
Huron Meadows	Sunset Ridge	55	3	1	2	1	Yes	Appears to meet all requirements	1,192	Completed 2019	0
Huron Meadows	Golf Course	118	5	1	5	1	Yes	Appears to meet all requirements	1,192	Completed 2019	0
Huron Meadows	Cedar Ridge	38	2	1	2	1	Yes	Appears to meet all requirements	1,192	Completed 2019	0
Indian Springs	Golf Course	116	5	5	5	1	Yes	Appears to meet all requirements.	Not available	Completed 2018?	0
Indian Springs	South Meadowlark	100	4	4	4	1	Yes	Appears to meet all requirements. Recommend moving spaces closer to the shelter when access walks are constructed.	Not available	Completed 2018?	0
Indian Springs	North Meadowlark	91	4	2	4	2	Yes	Appear to met all requirements.	Not available	Completed 2018?	0
Indian Springs	Environmental Discovery Center	103	7	7	5	1	Yes	Appears to meet all requirements.	Not available	Completed 2018?	0
Kensington	Administrative Office	74	3	2	3	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	West Boat Launch	208	8	3	7	2	Yes	Appears to meet all requirements.	1,040	Completed 2019	0
Kensington	Nature Center	92	4	1	4	1	Yes	Appears to meet all requirements.	1,040	Completed 2019	0
Kensington	Baywoods	196	7	2	7	2	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Spring Hill	59	4	1	3	1	Yes	Appears to meet all standards	1,040	Completed 2019	0
Kensington	Farm Center	117	6	2	5	1	Yes	Recommend grouping with the Farm Center Overflow lot total. 181 spaces will require 6 accessible spaces.	1,040	Completed 2019	0
Kensington	Farm Center Overflow (gravel)	60	0	0	0	0	Yes	Accessible spaces may be needed. Recommend grouping with the Farm Center parking lot total.	1,040	Completed 2019	0
Kensington	Shore Fishing	96	4	1	4	1	Yes	Appears to meet all standards	1,040	Completed 2019	0
Kensington	North Martindale	388	11	2	8	1	Yes	Appears to meet standards	1,040	Completed 2019	0
Kensington	South Martindale	395	8	1	8	1	Yes	Appears to meet standards	1,040	Completed 2019	0
Kensington	East Boat Launch Upper Lot	100	5	1	4	1	Yes	Appears to meet standards	1,040	Completed 2019	0
Kensington	Golf Course	123	5	1	4	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Boat Rental	191	6	2	5	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Maple Beach	631	10	0	10	3	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Playfield East	36	2	1	2	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	East Boat Launch Lower Lot	65	6	2	2	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	North Hickory	64	3	1	3	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Playfield North	52	3	1	3	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	South Hickory	101	5	1	5	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Turtlehead	131	6	2	5	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Possum Hollow Restroom	158	7	3	6	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	East Boat Launch / South Martindale	65	6	1	6	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Kensington	Orchard	74	4	1	3	1	Yes	Appears to meet all requirements	1,040	Completed 2019	0
Lake Erie	Cove Point (Muskrat Shelter)	34	2	2	2	1	Yes	Appears to meet all requirements.	673	Completed 2019	0
Lake Erie	Cove Point (Wood Duck Shelter and Restroom)	110	5	5	5	1	Yes	Appears to meet all requirements.	673	Completed 2019	0
Lake Erie	Marshlands Museum	141	6	6	5	1	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake Erie	Great Wave Area (bathhouse, pool, food bar)	382	18	4	8	2	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake Erie	Marina Point Fishing Pier	4	4	1	1	1	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake Erie	Marina	182	10	5	6	1	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake Erie	Golf Course	158	6	2	6	1	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake Erie	Boat Launch	196	7	2	6	1	Yes	Appears to meet all requirements	673	Completed 2019	0
Lake St. Clair	Nature Center	141	8	4	5	1	Yes	Appears to meet all requirements.	1,185	Completed 2019	0
Lake St. Clair	Lot A (Golf Course)	306	8	6	8	2	Yes	Appears to meet all requirements.	1,185	Completed 2019	0

PRIORITY 1. PRIMARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Total Spaces	Total # of HC Spaces	# that are Van Accessible	Required HC Spaces	Required Van Spaces	Space Meet All Requirements	Notes	Cost	Timeline	Priority Ranking
Lake St. Clair	Daysail	126	8	3	5	1	Yes	Appears to meet all requirements	1,185	Completed 2019	0
Lake St. Clair	Lot B	631	13	4	13	2	Yes	Appears to meet all requirements	1,185	Completed 2019	0
Lake St. Clair	Lot C	458	12	4	9	2	Yes	Appears to meet all requirements	1,185	Completed 2019	0
Lake St. Clair	Lot D	86	15	5	3	1	Yes	Appears to meet all requirements	1,185	Completed 2019	0
Lake St. Clair	Lot E	601	14	4	13	3	Yes	Appears to meet all requirements	1,185	Completed 2019	0
Lower Huron	Ellwoods North	161	6	3	6	1	Yes	Appears to meet all requirements. The combined total of 182 spaces require 6 accessible spaces. Striped aisles should be centered on the walks in the future.	539	Completed 2019	0
Lower Huron	North Fishing Site	20	1	1	1	1	Yes	Appears to meet all requirements.	539	Completed 2019	0
Lower Huron	Tulip Tree North	21	2	1	1	1	Yes	Appears to meet all requirements.	539	Completed 2019	0
Lower Huron	Tulip Tree South	43	4	3	3	1	Yes	Appears to meet all requirements.	539	Completed 2019	0
Lower Huron	Turtle Cove	269	8	2	7	2	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Walnut Grove Lot 1	42	4	2	2	1	Yes	Both parking areas appear to meet all requirements. Recommend moving the dumpster that is in the striped van aisle closest to the shelter.	539	Completed 2019	0
Lower Huron	Bob White Trail Lot	13	1	1	1	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	East Bend	49	2	1	2	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Woods Creek South	334	9	3	8	3	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	South Fishing Site	23	1	1	1	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Fox Woods	150	6	2	5	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Hawthorn Glade	140	5	2	5	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Sycamore Bend	90	4	1	4	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Woods Creek North	130	5	1	5	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Oakwoods	Nature Center	72	3	1	3	1	Yes	Appears to meet all requirements	685	Completed 2019	0
Stony Creek	Southdale/Go Ape Adventure	100	6	3	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Northdale	99	6	3	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Gladeview South	100	4	2	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Gladeview Restroom Parking	3	2	1	1	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Gladeview North	98	4	1	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Oakgrove West	105	5	2	5	2	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Oakgrove Restroom Parking	3	2	1	1	1	Yes	Appears to meet all requirements	700	Completed 2019	0
Stony Creek	Oakgrove North	138	5	2	5	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Ridgewood East	72	4	1	3	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Ridgewood West	95	4	1	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Lakeview	100	4	1	4	1	Yes	Appears to meet all requirements	700	Completed 2019	0
Stony Creek	Osprey Lot	12	0	0	0	0	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Nature Center	77	4	2	4	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Baypoint Beach	668	14	4	14	3	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Mt. Vernon / Boat Rental	150	5	2	5	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Winter Cove North	109	5	2	5	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Winter Cove South	187	6	1	6	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	West Branch North (East Lot)	46	3	1	2	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	West Branch North (West Lot)	38	3	1	2	1	Yes	Appears to meet all requirements. Recommend grouping some of the West Branch South lot totals with this lot.	700	Completed 2019	0
Stony Creek	West Branch West	54	3	1	3	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	West Branch East	58	3	1	3	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Stony Creek	Shore Fishing	42	2	1	2	1	Yes	Appears to meet all requirements	700	Completed 2019	0
Stony Creek	Boat Launch	266	7	3	5	2	Yes	Appears to meet all requirements	700	Completed 2019	0
Willow	Washago Pond Picnic Shelter	51	2	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Willow Pool	580	12	2	12	2	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Golf Course	122	6	1	5	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Golf Course Driving Range	25	1	1	1	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Washago Pond Rental Facility	96	4	1	4	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Fox Meadows	79	5	1	4	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Big Bend 1	36	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Big Bend North	64	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0

PRIORITY 1. PRIMARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Total Spaces	Total # of HC Spaces	# that are Van Accessible	Required HC Spaces	Required Van Spaces	Space Meet All Requirements	Notes	Cost	Timeline	Priority Ranking
Wolcott Mill	Farm Center Service Yard	0	0	0	0	0	Yes	An accessible space may be required. Low priority.	470	Completed 2019	0
Wolcott Mill	Farm Center	109	5	3	5	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Wolcott Mill	Historic Center (authorized parking area)	10	1	1	1	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Wolcott Mill	Historic Center	106	2	1	0	0	Yes	Appears to meet all requirements	470	Completed 2019	0
Wolcott Mill	Camp Rotary Activity Center	17	1	1	1	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Wolcott Mill	Camp Rotary Restrooms	2	2	1	1	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Wolcott Mill	Camp Rotary Picnic Shelter	17	2	1	1	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Delhi	East Delhi - South Lot	184	0	0	6	1	Yes	Recommend grouping both parking lot totals and adding a seventh space in the southeast corner of the south lot by the aggregate service road and baseball field. 290 spaces requires 7 spaces. Leave parking space aggregate.	To be determined	2027	4
Stony Creek	Eastwood Beach	716	14	4	14	3	Yes	Add a crosswalk marking for access aisle adjoining accessible route. Recommend relocating a couple of spaces closer. Lot goes into overflow frequently. May want to add additional accessible spaces for these days.	To be determined	2027	4
Stony Creek	West Branch South Lot	57	3	1	3	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Kensington	Windfall Hill	83	4	2	4	2	Yes	Accessible route to shelter, not high priority	To be determined	2029	5
Lake Erie	Shore Fishing	16	1	1	1	1	Yes	Appears to meet all requirements	470	Completed 2019	0
Stony Creek	Golf Course	102	5	2	5	1	Yes	Appears to meet all requirements	470	Completed 2019	0

Accessibility Ranking (listed by park in order of importance based on project factors)

Rating	Description
1	Very high demand for an accessible path. Locations of facilities are appropriate, construction costs are often low, and use is very high. Potential safety concern. Recommend year 1 to 2 implementation.
2	High demand for an accessible path. Locations of facilities are appropriate. Project costs are a little more substantial and use of facility is often a little less. Potential safety concern. Recommend year 3 to 4 implementation.
3	Medium demand for an accessible path. Locations of facilities may be questionable. Project costs are more substantial and use of facility is much less. Recommend year 5 to 6 implementation.
4	Very low demand for an accessible path or project location is questionable. Access may need to wait until facility location is improved. Access is rarely needed or cost prohibited at these locations. Use of area may be extremely low. Recommend year 7 to 8 implementation.
5	Extremely low demand for accessible path or project location is extremely questionable. Access is often not needed in these locations. Recommend year 9 to 10 implementation.

PRIORITY 1. PRIMARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Description	Justification/Solution	Cost	Timeline	Priority Ranking2
Willow	Washago Pond South Lot	Improved access desired to soccer fields from the parking lot access drive. Culvert needed.	Access is needed along the access drive to the south lot. Wood decking is currently in place to bridge the drainage swale. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	Completed	0
Dexter-Huron	Northwest Parking Lot	Access walk desired from the west parking lot to the hike-bike trail. Could be part of the B2B trail project.	Heavily used trailhead. Worn path used as this time does not provide good access for strollers, rollerblades, etc. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Huron Meadow	Acorn Ridge	Accessible walks desired connecting the parking lot, picnic shelter, restrooms, and accessible playground. 470' of path needed. Accessible parking spaces should be moved closer to the shelter.	Popular area for a variety of activities. No access paths at this time. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Indian Springs	Shelters C, D, & E	Access walks desired to the three small rental shade structures.	Very short segments required. 70' total. Accessible tables have been ordered for these shelters. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Indian Springs	North Meadowlark	Improve access desired connecting the Spray 'N' Play and South Meadowlark restroom building.	Should be grouped with other access improvement projects. 280' of path required. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Indian Springs	North Meadowlark	Accessible walk desired connecting the parking lot, shelter, and restrooms.	Will likely become the more popular shelter when the North Martindale playground is removed. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Indian Springs	South Meadowlark	Accessible walk desired connecting the parking lot, shelter, and restrooms.	When the Meadowlark playground is removed this may become less popular than the North Martindale. This also requires a longer path. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2021	1
Kensington	Boat Rental	Reconstruct accessible ramps and relocate handicap parking spaces.	One of our most used facilities in the park. Group with the connector to the hike-bike trail in the same area. Ramp needs handrail extensions at the top and bottom of the ramp that extend out at least 12" and are parallel to the ground surface. Comply with all other ramp standards.	To be determined	2021	1
Kensington	Boat Rental	Accessible walk desired linking the hike-bike trail to the boat rental facility.	One of our most used facilities in the park. Group with the handicap ramps in the same area.	To be determined	2021	1
Kensington	Maple Beach	Improved ramp access desired with 6' flares.	Reconstruct ramp as part of the Maple Beach Redevelopment. Short trail segment required.	To be determined	2021	1

Kensington	Maple Beach	Accessible path desired from the parking lot to the hike-bike trail.	Reconstruct ramp as part of the Maple Beach Redevelopment. Short trail segment required.	To be determined	2021	1
Kensington	Nature Center	Accessible walk desired to and in front of the trailhead structure.	Busy trailhead. Very small area needing aggregate.	To be determined	2021	1
Kensington	North Martindale Beach Connector Trail	Accessible walk desired connecting the North Martindale picnic area to the Beach Activity Area. 270' of walk needed to connect existing paths.	There is no access between the North Martindale shelter and Beach Activity Area at this time. One of the most rented shelters in the park.	To be determined	2021	1
Kensington	South Martindale Connector Trail	Accessible walk desired connecting the South Martindale path to the Beach Activity Area. 420' of walk needed.	Safety concern, trail outlets at main drive into Martindale Beach. Other option is to remove the South Martindale Beach path.	To be determined	2021	1
Kensington	Nature Center	Accessible walk desired connecting the hike-bike trail to the Nature Center.	Try and draw trail users to the Nature Center.	To be determined	2021	1
Kensington	North Hickory	Accessible walk desired connecting the parking lot, picnic shelter, and restroom building.			Completed	1
Kensington	West Boat Launch Finger Piers	Accessible finger piers and access to the finger piers desired at the boat launch.	Very busy launch area.	To be determined	2021	1
Kensington	Orchard	Fix asphalt opening on route greater than 1/2 inch. Fix gap in concrete of door entrance threshold	Remove this section and provide a surface that is firm and stable and gaps no wider than 1/2" and no deeper than 1/2"	To be determined	2021	1
Lake St. Clair	Daysail Shelter	Recommend moving the accessible parking spaces closer to the shelter. Requires removal of a parking bumper.	Easily accomplished.		Completed	1
Lake St. Clair	Seawall Shelter	Accessible walk desired connecting the parking lot and shelter. Recommend including with the next phase of the parking lot.	Heavily used shelter. Construction should be occurring nearby shortly.	To be determined	2021	1

Lake St. Clair	West Beach Shelter	Accessible walk desired connecting the shelter, parking lot, and restrooms. Recommend constructing these walks as part of a future trail project that connects the Daysail area to the Beach area.	Heavily used shelter. Trail to day sail lot is heavily used as well.	To be determined	2021	1
Lake St. Clair	Voyageur Shelter	Access path desired to voyageur canoe launch	Walkway desired from lot to the launch area.	To be determined	2021	1
Oakwoods	Nature Center	Improved ramp access desired. Recommend moving the spaces closer to the main walks.	6' flares required on ramps. Poor access to Nature Center at this time. 2018 MNTF Grant pursuit will provide proposed asphalt pavement repair to flatten new accessible parking area with walkway.	To be determined	2021	1
Stony Creek	Baypoint Beach	Accessible walk desired connecting the hike-bike trail and picnic shelter. Recommend including an accessible grill with projects like these.	Very short trail segment. Rented frequently. Project has already been designed.	To be determined	2021	1
Stony Creek	West Branch West	Accessible walk desired connecting the picnic shelter and restroom building. Recommend including a walk towards the West Branch East shelter across the street and roadside parking area at the same time.	Heavily used picnic area without access walks. Project has already been designed.	To be determined	2021	1
Stony Creek	Oakgrove North	Accessible walk desired connecting the shelter and restroom building.	415' section of walk needed.	To be determined	2021	1
Stony Creek	West Branch East	Accessible walk desired connecting the parking lot, shelter, and restroom building.	Recommend grouping with the West Branch West access walks.	To be determined	2021	1
Stony Creek	Winter Cove North	Accessible walk desired connecting parking lot, adjacent shelters, restroom building, and the accessible playground.	Recommend relocating the shelter so it is on the same side as the restroom building and closer to the water and playground.	To be determined	2021	1
Stony Creek	Oakgrove Playground	Accessible walk desired connecting the parking lot, restroom building, and accessible playground.	Recommend moving the playground on the same side as the shelters and restroom building.	To be determined	2021	1

Stony Creek	Boat Rental	Accessible walk to boat rental	Create a stable, firm and slip resistant accessible route to boat rental.	To be determined	2021	1
Willow	Pool Shelter	Accessible walks desired connecting the shelter, parking lot, and pool activity area.	Shelter was recently constructed. New construction must meet ADA requirements.	To be determined	2021	1
Willow	Fox Meadows	Accessible walk desired connecting the south shelter to the Pool Activity Area. 400' of walk needed.	Poor access to the Pool area at this time.	To be determined	2021	1
Willow	Fox Meadows	Accessible walk desired connecting the parking lot, north shelter, and restrooms. 300' of trail needed. Recommend including the an accessible walk to the hike-trail with this project. 190' of trail needed.	Has access to the pool but not to the restroom building or the hike-bike trail.	To be determined	2021	1
Willow	Big Bend Restrooms	Improved pavement desired at a walk near the restrooms.	Pavement needed instead of the aggregate repair that was made.	To be determined	2021	1
Willow	Indian Ridge	Accessible walks desired connecting the parking lot, restrooms, and hike-bike trail.	Vault latrines don't meet ADA requirements. This is the only lot in the area with hike-bike trail access.	44,100	2021	1
Willow	Big Bend Trail Access	Accessible walk desired from the upper roadside parking lot to the hike-bike trail. As part of the project an ADA picnic table and an ADA drinking fountain can be updated with access from the hike-bike trail. 165' of trail needed.	Short trail segment needed. Access to restrooms is far away. Drinking fountain is close to the trail.	23,100	2021	1
Willow	Big Bend Kayak Launch	Accessible walk desired connecting the parking lot, kayak launch, and an accessible picnic table. 245' of trail needed.	The kayak launch does not meet ADA requirements. Long trail segment for the amount of use.	To be determined	2021	1
Hudson Mills	Activity Center	Accessible walk desired to and in front of the nature trail trailhead.	Access should be provided to all trailheads.	To be determined	2023	2

Huron Meadows	Sunset Ridge	Accessible walk desired to and in front of the new trailhead. Recommend aggregate surface at this time.	Improved access desired. Very small project.	To be determined	2023	2
Huron Meadows	Cedar Ridge	Recommend paving the accessible parking spaces that are there. Spaces and signs do not align with the paved access path.	Area is used for a variety of year-round activities. Busier than you might expect.	To be determined	2023	2
Lake Erie	Marshlands Museum	Accessible walk desired connecting the parking lot, eagle enclosure, boat house, and trail.	Nature trails are flat and can be made accessible fairly easily.	26,000	2023	2
Lake Erie	Cove Point	Accessible walk desired to the vault latrines.	Adjoin access aisle to accessible route (create accessible route). Main entrance needs to be leveled.	10,600	2023	2
Lake St. Clair	North Marina Shelter	Access path desired from the boat launch drop-off area. Access is provided at this time from the main park road drop-off area.	The alternate accessible route location would have to be signed if an accessible route is not provided from this location. Recommendation is to have accessible routes from both drop-off areas.	To be determined	2021	2
Lower Huron	Woods Creek Ramps	Improved ramp access desired at two locations.	6' flares required on ramps. Fix concrete	To be determined	2023	2
Stony Creek	Gladeview North	Accessible walk desired connecting the shelter and restroom building.	Has an existing path to the shelter, but no path to the restroom building. Heavily used by disc golfers.	To be determined	2023	2
Dexter-Huron	East Shelter	Access walk desired connecting the East Picnic Shelter to parking, restrooms, and the hike-bike trail. Include as part of the B2B trail project.	There are no access walks to the East Picnic Shelter from either of the east parking lots.	To be determined	2025	3
Dexter-Huron	West Shelter	Access walk desired connecting one of the west parking lots and the West Picnic Shelter. Shelter has access to the restroom building.	Oldest shelter in the park system. May need to be moved because of the Natural Rivers Area when it is time to replace.	To be determined	2025	3
Hudson Mills	Activity Center	Accessible walk desired connecting the shelter, parking, and Activity Center restrooms.	Other projects have been discussed that may impact this path. These include a spray pad and new restroom building. Adjust activity center door closer so it meets 5 seconds to close standard. Secure carpet at door entrance at edges.	To be determined	2025	3

Kensington	Farm Center	Improved access desired at the Farm Center. Walks exceed 5% in many locations. Recommend signing the accessible routes within the facility.	Very busy part of the park. The area should have accessible facilities.	To be determined	2025	3
Kensington	South Martindale Drop Off Area	Accessible ramp desired at the drop off area to the beach.	Other ramps are provided nearby but not at the preferred location where the walks split.	To be determined	2025	3
Kensington	South Martindale Shelter	Accessible walks desired connecting the picnic shelter and restrooms.	No access walks at this time. Reconsider restroom building location to minimize walks and increase use of facilities.	To be determined	2025	3
Kensington	West Playfield	Accessible walks desired connecting the parking lot, restrooms, remote shelter, and remote accessible playground.	No access walks at this time. Consider relocating shelter and playground closer to a lot in the future.	To be determined	2025	3
Kensington	South Martindale Shelter	Improved access from accessible spaces desired.	Walkway desired in front of parking spaces to avoiding using the drive aisle	To be determined	2025	3
Kensington	Possum Hollow Restroom	Bathroom entrance needs concrete repair.	Remove this section and provide a surface that is firm and stable	To be determined	2025	3
Lake Erie	Great Wave	Accessible walks desired connecting both shelters to the existing porta johns. Recommend relocating the porta-johns to an easily accessible location from both shelters. May require an additional porta-john, one for each shelter.	Recommend moving one of the shelters in the future and locating it on the same side with access to a new restroom building.	14,700	2025	3
Lake St. Clair	Lot D	The path to warming shelter is not accessible	Remove this section and provide a surface that is firm and stable	To be determined	2025	3
Lower Huron	South Fishing Bike Rack	Accessible walk desired to the bike rack.	Access to small items like these still need access routes.	To be determined	2025	3
Oakwoods	Cedar Knoll	Accessible walk desired connecting the parking lot and restrooms. Access to a kayak launch should be considered.	Little used picnic area. Vault latrines are not accessible.	85,905	2025	3

Stony Creek	Mt. Vernon / Boat Rental	Accessible walk desired connecting the boat rental facility and restrooms. Recommend constructing an access path to the Voyageur Canoe Launch at the same time. Need to determine plans for this project.	Our highest used area without an accessible walk. There is uncertainty on the plans and timing of its replacement.	To be determined	2025	3
Stony Creek	Winter Cove South	Accessible walk desired connecting the parking lot, adjacent shelters, and the accessible playground.	Recommend grouping this project with the access walks to Winter Cove North. Remove this section and provide a surface that is firm and stable	To be determined	2025	3
Willow	Flintwoods Fountain	Accessible drinking fountain desired. Fountain along the paved walk doesn't meet ADA requirements.	Replacing drinking fountains along paved walks can be accomplished easily compared to those out in turf areas.	16,000	2025	3
Hudson Mills	Pine View	Accessible walk desired connecting the parking lot and hike-bike trail.	Short segment of trail needed. Access path will provide improved access for runners, strollers, in-line skaters, etc.	To be determined	2027	4
Kensington	West Boat Launch	Accessible walk desired connecting the picnic shelter and restrooms. Recommend modifying walk alignments around the restroom building and improving access to the hike-bike trail near the restrooms at the same time.	Heavily used area. Some topography issues. 2018 MNTF Grant pursuit would include proposed 6' width concrete walks and barrier free parking connecting to proposed kayak launch, vault latrine, accessible table and grill, and existing picnic shelter.	To be determined	2027	4
Kensington	Living History Area	Accessible walks desired to and around the Living History Area.	Popular area for a variety of activities. Area continues to grow. No access at this time.	To be determined	2027	4
Kensington	Shore Fishing	Accessible walks desired connecting the parking lot and restrooms. Access to the kayak launch area should be considered.	No access walks or accessible parking at this time.	To be determined	2027	4
Lake St. Clair	Nature Center Drop Off Area	Ramped access desired from the drop off area.	Ramps are located near the accessible parking spaces but not at the drop off area in front of the building.	To be determined	2027	4
Stony Creek	West Branch North	Accessible walk desired connecting the parking lot, restrooms, and basketball court.	Recommend redevelopment of this picnic area. Shelter relocation and lot reconfiguration can reduce the amount of walks needed and improve safety and circulation in the area. More parking may be desired for the mountain biking trails if redeveloped.	To be determined	2027	4

Stony Creek	Baypoint Beach	Accessible walk desired connecting the parking lot, restrooms, and the basketball court.	Plans for the redevelopment of the beach show the basketball court remaining.	To be determined	2027	4
Willow	Washago Pond Center Lot	Improved access desired to the soccer fields when wet. Culvert needed.	South lot is closer and used more frequently for soccer field access. Provide a surface that is firm and stable	To be determined	2027	4
Wolcott Mill	Camp Rotary	Accessible walks desired connecting an accessible camp site, fire ring, and restrooms.	Accessible camp sites may be desired.	To be determined	2027	4
Hudson Mills	Golf Course	Improved ramp access desires in two locations along with striping to ensure ramps can be accessed.	Ramps are not built to current standards. 6' flares required. Regrade curb ramp or move closer.	To be determined	2029	5
Hudson Mills	Activity Center	Accessible walk desired to the shuffleboard courts.	Very short connector required. Fairly new court. Very little use.	To be determined	2029	5
Hudson Mills	Activity Center	Accessible walk desired connecting the paved path and basketball court.	Court is remote. Consider a new location. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Hudson Mills	Pine View	Accessible walks desired connecting the parking lot, picnic shelter, and restrooms. Recommend grouping with the access path to the hike-bike trail. Consider eliminating shelter and need for long paved park road. Recommend relocating the shelter to the Activity Center with a new accessible restroom building.	One of the least rented shelters in the park. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Hudson Mills	Maintenance Yard	Accessible ramp desired from the employee parking lot.	An accessible parking space may be required.	To be determined	2029	5
Hudson Mills	Activity Center	Accessible walk desired to the playground drinking fountain.	Drinking fountain is not an accessible fountain. Relocation of fountain recommended. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Hudson Mills	Group Camp	Accessible walks desired connecting parking, restrooms, fire ring, and a campsite.	Recommend having one accessible camp site. Low priority.	To be determined	2029	5

Hudson Mills	Oak Meadows	Accessible walk desired connecting the parking lot and restrooms.	Vault latrines are very remote and not accessible. Used primarily by disc golfers. The shelter in this area was removed. A restroom building could be consider in the future as part of an athletic field complex.	To be determined	2029	5
Hudson Mills	Fishing Site	Accessible route desired	Recommend having one accessible parking space and route. Low priority.	To be determined	2029	5
Huron Meadow	Golf Course	Improved ramp access desired. 6' flares required on ramps. Recommend adding a walk in front of vehicles to avoid access route in parking lot. Ramp could be moved closer to the accessible spaces.	Improved access desired.	To be determined	2029	5
Indian Springs	Golf Course	Improved ramp access desired.	6' flares required on ramps.	To be determined	2029	5
Kensington	Mitten Bay	Accessible walks desired connecting the parking lot, restrooms, and walks around the marina.	Some topography issues and lengthy walk needed. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Kensington	South Hickory	Accessible walks desired connecting the parking lot, picnic shelter, and restrooms.	No access walks at this time. Topography makes this difficult. Consider relocating shelter.	To be determined	2029	5
Kensington	Baywoods	Accessible walk desired connecting the restroom building and picnic shelter.	No access walk at this time. Topography makes this difficult. Consider relocating shelter in the future.	To be determined	2029	5
Kensington	Park Office	Improved ramp access desired.	6' flares required on ramps.	To be determined	2029	5
Kensington	Boat Rental	Accessible walks desired connecting the parking lot, boat rental building, and kayak launch area.	Topography issues and there is not an accessible launch at this time.	To be determined	2029	5
Lake St. Clair	Boat Launch	Accessible walk desired connecting the parking lot and excursion boat pick-up area on the south side.	It is unclear if the excursion boat pick-up location has been moved to a different location. Consider moving to a location that is already accessible. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Lake St. Clair	Nature Center	Accessible walk desired to the fire pit location.	Not used frequently. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5

Lower Huron	Hawthorn Glade / Ellwoods	Accessible walks desired connecting restrooms, parking, the accessible playground, accessible drinking fountain, the North and South Shelter, and Turtle Cove.	These picnic areas are used heavily and provide access to Turtle Cove without having to cross a road. Recommend locating the South shelter closer to parking. Access walks can be minimized in the future with different shelter and restroom locations. This is one of the few restrooms in the park system without accessible walks.	To be determined	2029	5
Lower Huron	Tulip Tree	Accessible walk desired connecting the shelter, restrooms, and accessible drinking fountain.	The shelter and restroom building are on opposite sides of the road. Recommend locating both on the same side in the future or removing the shelter if camping were ever to expand. Consider removing the drinking fountain or relocating along a walk.	To be determined	2029	5
Stony Creek	West Branch North	Accessible walk desired connecting the shelter and restrooms.	Recommend redevelopment of this picnic area. Perhaps move the shelter and west lot. Double the size of the east lot so all facilities are located on the same side of a lot.	To be determined	2029	5
Stony Creek	Southdale	Accessible walk desired connecting the parking lot, restroom building, and shelter.	Future plans uncertain with Go Ape, however, popular picnic area.	To be determined	2029	5
Stony Creek	Oakgrove West	Accessible walk desired connecting the parking lot, picnic shelter, and restroom building.	Topography issues. Recommend relocating shelter in the future.	To be determined	2029	5
Stony Creek	Southdale	Accessible walk desired connecting the parking lot and basketball court.	Recommend relocating court to make it closer in the future.	To be determined	2029	5
Stony Creek	Northdale	Accessible walk desired connecting the parking lot and basketball court.	85' section needed between the parking lot and court. Much longer if access is provided to the restroom building.	To be determined	2029	5
Stony Creek	Gladeview South	Accessible walk desired connecting the shelter and restroom building.	Little used picnic shelter. Topography issues. Recommend relocating shelter to another picnic area or removing.	To be determined	2029	5
Stony Creek	Mt. Vernon	Accessible walk desired connecting the parking lot, restrooms, and picnic shelter.	Topography issues. Recommend relocating the shelter to an accessible location in the future. Perhaps where the boat rental building is located if that facility is moved to Baypoint Beach.	To be determined	2029	5
Stony Creek	Golf Starter Building	Accessible walk from parking spaces needs regrading	Regrade accessible spaces and access aisles no steeper than 1:48 in all directions (or reconfigure with paint if there are acceptable slope/location options for accessible parking.	To be determined	2029	5
Willow	Washago Pond South Lot	Improved access desired to soccer fields when wet. Culverts needed. Improved access is also desired to the hike-bike trail. Recommend combing both projects.	Soccer field access was discussed earlier this year as a project staff could do. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5

Willow	Golf Course	5 accessible signs missing. 2 van signs missing. Curb ramp threshold steeper than 1:12	Regrade curb ramp no steeper than 1:12.	To be determined	2029	5
Willow	Chestnut Restrooms	Accessible walk desired connecting the Chestnut East shelter to one of the restroom buildings. 440' of walk needed.	Consider moving out of the floodplain to another area that already has a restroom. Co-locate restrooms, playgrounds and shelters on the same side of a lot. Consider eliminating this shelter.	To be determined	2029	5
Willow	Acorn Knoll Restrooms	Accessible walks desired connecting the parking lot and restrooms.	Other picnic areas are more popular. Vault latrines don't meet ADA requirements.	To be determined	2029	5
Willow	Dance Pavilion	60" turning radius required at top of ramp.	Ramp design is not perfect but works. Low priority.	To be determined	2029	5
Wolcott Mill	Camp Rotary	Accessible walks desired to the spectator viewing areas at the 4-H arenas.	Used infrequently. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36"	To be determined	2029	5
Wolcott Mill	Camp Rotary	Accessible walk desired connecting the parking lot, Camp Rotary shelter, and restroom building.	Used infrequently. 375' of walk needed.	To be determined	2029	5
Wolcott Mill	Historic Center	Accessibility issues based on topography	Topography issues at Historic Center. Two paths diverge prior to Historic Center. Directional sign to the Mill Race paved approach exceeds grade requirements and cross slopes. For ADA use ramp, with directional sign to bathroom.	To be determined	2029	5

Amenities ranked 1 through 32 (1-6 implemented by year 2, 7-12 implemented by year 4, 13-18 implemented by year 6, 19-24 implemented by year 8, and 25-31 implemented by year 10)	Generalized Priority Ranking
Accessible Parking	1
Accessible Routes and Ramps (Paved)	2
Accessible Door Openers / Knobs	3
Accessible Restrooms	4
Accessible Port-a-John Facilities	5
Accessible Picnic Shelters	6
Accessible Tables	7
Accessible Trails (Aggregate)	8
Accessible Playgrounds	9
Accessible Pools / Spray Pads	10
Accessible Service Counter Window	11
Accessible Drinking Fountains/Water Refill Stations	12
Accessible Coat Racks / Hangers in Restrooms	13
Accessible Fishing Dock	14
Accessible Golf Carts	15
Accessible Hayrides	16
Accessible Boat Ramps	17
Accessible Marina Slips	18
Accessible Waterfronts / Beaches	19
Accessible Livery Facilities	20
Accessible Grills	21
Accessible Kayak Launches	22
Accessible Work Environments	23
Accessible Camp Sites / Group Camp Sites	24
Accessible Equestrian Staging Areas	25
Accessible Shuffleboard Courts	26
Accessible Basketball Courts	27
Accessible Baseball Fields	28
Accessible Soccer Fields	29
Accessible Bike Racks	30
Accessible Sand Volleyball Courts	31
Accessible Disc Golf Facilities	32
Prioritization for placement of an accessible drinking fountain, table, etc. will often be based on the areas frequency of use. The following areas are considered priority areas with generalized priority ranking following implementation years 1-10+	Generalized Priority Ranking
Hike-Bike Trail	1
Activity Center / Central Plaza	1
Nature Center, Museum, Historic Center, Environmental Education Center	2
Farm Center	2
Beach	3
Pool / Spray Pad	3
Heavily Used Rental Shelters	4
Boat Rental Facility	4
Canoe / Kayak Livery	5
Food Venue	5
Golf Course	5
Venue (equity ranking considered in priority ranking)	Equity Ranking Scale
Free - Broad Based Recreation	1
Some Cost Associated - Purchase of Equipment	2
Small Fee Associated - \$2-\$24	3
Large Cost Associated - Purchase of a Boat / Horse	4
Large Fee Associated - \$25 plus - Exclusive Club, Narrowly Focused	5
Venue (equity ranking considered in priority ranking)	Equity Ranking
Nature Center	1
Farm Center	1
Picnic Areas	1
Running and Walking Trails	1
Beach	1
Spray Pad	1
Restrooms	1
Mountain Biking Trails	2
Field Sports and Courts	2
Fishing Docks	2
Picnic Shelter	2
Cross Country Skiing	3
Pool	3
Camping	3
Boat Rental	3
Disc Golf	3
Adventure Golf	3
Group Camp	3
Equestrian Facilities	4
Boat Launch	4
Canoe / Kayak Livery	4
High Ropes Course	4
Golf	5
Marina	5

PRIORITY 2. ACCESS TO GOODS AND SERVICES RECREATIONAL VISITOR AREAS (Renovations, Replacements, and Additions)

Park	Location	Description	Justification/Solution	Cost	Timeline	Priority Ranking
Wolcott Mill	Camp Rotary Activity Center	Counter service areas in compliance	Meets ADA requirements.	Not available	Completed	0
Hudson Mills	Activity Center	Door closer needs adjusting, carpets need to be secured	Popular facility for events. Provide a mat with a heavier backing or tape the mat to the floor. Add closer.	To be determined	2021	1
Indian Springs	EDC	Lower signs and raise letters/braille. Clear floor space for light switches not met. Service counters for both main counter and banquet room exceed height limit	Does not meet requirements.	To be determined	2021	1
Kensington	Nature Center	Nature Center needs minor ADA improvements.	Clear floor space for light switches, door knobs	To be determined	2021	1
Lake St. Clair	Nature Center	Restrooms need accessibility improvements, building entrance mat needs to be secured, clear floor space to light switches needed, service counter higher than 36", fish tank and display obstructing counter clear floor space	Expand restrooms into interpretive area. Other improvements needed for ADA. Provide a mat with a heavier backing or tape the mat to the floor.	To be determined	2021	1
Oakwoods	Nature Center	door handles need new hardware, garbage bin within light switch clear floor space, service counter exceeds height max.	Does not meet requirements. MNTE Grant currently being pursued.	To be determined	2021	1
Lake Erie	Museum	Goods and services need accessibility improvements	Ramp appears to not meet standards. Sign for classroom does not meet standards, update sign. Service counter above 36 inches.	To be determined	2023	2
Lake St. Clair	Par-3 and Group Rental Shelter	Accessible picnic unit for this shelter desired.	Not in compliance with ADA	To be determined	2023	2
Willow	Willow Pond Rental	Hardware does not meet height requirements, carpet not secured, service counter exceeds height max.	Does not meet requirements. Provide a mat with a heavier backing or tape the mat to the floor. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in alterations.	To be determined	2023	2
Wolcott Mill	Farm Center/Office	Goods and services needed.	Signs designating permanent rooms do not meet standards. Front approach to interior rooms and light switches for public do not meet standards. Service counter does not meet 36 inch height maximum. Secure carpets.	To be determined	2023	2
Kensington	Boat Rental	Service Counter, Signs	Does not meet requirements.	To be determined	2025	3
Lake St. Clair	Point Walk Drinking Fountains	Accessible drinking fountains desired. Wider walks needed along with new fountains.	Paved walks lead to drinking fountains that are not accessible.	To be determined	2025	3
Lower Huron	Turtle Cove	Ramps, signs, and service counters.	Does not meet requirements.	To be determined	2025	3
Stony Creek	Eastwood Beach	Service Counters for slide area and food area	Does not meet requirements. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in	To be determined	2025	3
Stony Creek	Boat Launch Building	Signs, Service Counter	Does not meet requirements. Adjust signs and provide a section of counter that is 28 inches to 36 inches and is at least	To be determined	2027	4
Willow	Food Bar	Seating area, service counter.	Does not meet requirements. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in	To be determined	2027	4
Huron Meadows	Golf Starter Building	Service Counter	Does not meet requirements. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in	To be determined	2029	5
Indian Springs	Golf Starter Building	Service Counter	Does not meet requirements. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in	To be determined	2029	5
Lake Erie	Golf Course	Goods and services accessibility improvements	Appears to meet all requirements	Not available	Completed	0
Lake Erie	Food Bar	Goods and services accessibility improvements	Service counter above 36 inches. provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in	To be determined	2029	5
Lake Erie	Marina Building	Goods and services accessibility improvements.	Interior doors do not meet threshold vertical height limit. Carpet is not secured along edges. Move garbage can from obstructing light switch. Service counter is higher than 36 inches.	To be determined	2029	5
Stony Creek	Golf Course Starter Building	Service Counter	Does not meet requirements. Provide a section of counter that is 28 inches to 36 inches and is at least 24 inches long in alterations.	To be determined	2029	5
Willow	Golf Course Starter Building	Carpets not secure	Does not meet requirements. Provide a mat with a heavier backing or tape the mat to the floor.	150	2029	5

PRIORITY 3. RESTROOMS THAT SUPPORT PRIMARY RECREATIONAL VISITOR AREAS (Renovations, Replacements, and Additions)

Park	Location	Description	Justification/Solution	Cost	Timeline	Park Ranking2
Oakwoods	Nature Center	Restrooms need accessibility improvements	Signs to accessible location, adjust sign height, womens bathroom does not meet front approach standards, mirror and counter exceeds height limit, grab bars	To be determined	2021	1
Indian Springs	EDC	Restrooms need accessibility improvements	Grab bar adjustment. Provide a side grab bar a minimum of 42" long and a maximum of 12" from th corner. The grab bar should be mounted 33" to 36" to the top of the grab bar. Stall door needs closer and door pull	To be determined	2021	1
Kensington	Farm Center	Restroom building needed.	Popular area used for many activities	To be determined	2021	1
Kensington	Nature Center	Restrooms need accessibilty improvements. Recently renovated but not to ADA standards.	Sign not on latch side, change door swing and latch side of outside door to bathrooms, change door swing but not latch side of inside door of bathrooms. Mirror greater than 40 inches. Soap dispenser greater than 44 inches. Centerline of water closet exceeds 16-18 inches. Clearance of stall closet not met. Grab bar adjustments, door pulls needed for stalls.	To be determined	2021	1
Lake Erie	Museum	Restrooms need accessibility improvements	Alter toilet room for clear floor space. Lower lavatory mirror.	To be determined	2021	1
Lake St. Clair	Nature Center	Restroom door needs threshold needs to be replaced, women counter surface exceeds height compliance, lavatory pipes need insulating, toilet water closet needs toilet or partition moved, water closet needs altering for clearance width, grab bars need relocating if constructed after 2012, flush control and toilet paper dispenser (if constructed after 2012) need to move, door handles need door pulls if constructed after 2012	Expand restrooms into interpretive area, ADA standards. Replace threshold for a smooth transition. Remount the counter in the womens restroom no higher than 34". Relocate the toilet with a centerline 16" to 18" from the wall with flush control on open side and remount the toilet paper dispenser minimum 7" to a maximum of 9" in front of the toilet, no lower than 15", no higher than 48" and do not mount behind side grab bar. Provide a side grab bar a minimum of 42" long and a maximum of 12" from th corner. The grab bar should be mounted 33" to 36" to the top of the grab bar.	To be determined	2021	1
Delhi	West Delhi	One of the last remaining old style pit toilets in the park system. Consider moving closer to the parking lot and kayak launch / take-out.	Popular area for paddlers.	To be determined	2023	2
Hudson Mills	B2B Trail / Skips	Restroom building needed.	Consider adding a facility that can be used by Skips users as well as hike-bike trail users.	To be determined	2023	2
Huron Meadows	Sunset Ridge	Restrooms need accessibility improvements	Front approach entrance does not meet 18" maneuvering clearance, adjust coat hook and grab bars, door needs closer and handles.	To be determined	2023	2
Lower Huron	North Fishing Site	One of the last remaining old style pit toilets in the park system.	Heavily used facility without accessible facilities. Use of this area will increase when the parking lot is expanded. Frequent flooding results in river polution. Proposed new ADA vault toilets with DNR grant currently being pursued.	To be determined	2023	2

Lower Huron	South Fishing Site	Restroom building needed.	Popular trailhead, fishing, and kayak launch site. No facilities at this time. Difficult to justify for such a small parking lot.	To be determined	2023	2
Willow	Elder Creek	One of the last remaining old style pit toilets in the park system.	Recommend removing. Flush restrooms are available between the two parking lots.	To be determined	2023	2
Willow	Acorn Knoll	One of the last remaining old style pit toilets in the park system. Consider moving to the start of the disc golf course or adjusting the course so it starts from a paved lot closer to the restrooms.	Popular disc golf and picnic area.	To be determined	2023	2
Willow	Indian Ridge	One of the last remaining old style pit toilets in the park system.	Consider removing this picnic area. Lot's of infrastructure for the amount of activities in the area / use of the area.	To be determined	2023	2
Wolcott Mill	North Branch Trails	Restrooms needed.	Have discussed adding a prefab restroom building. No restrooms at this time.	To be determined	2023	2
Wolcott Mill	Farm Center/Office	Restroom renovations needed.	Accessible route greater than 5% and less than 8%, follow ramp standards or re-grade. Lower signs, door closer, lower mirrors, coat hooks, stall front approach and width not in compliance.	To be determined	2023	2
Hudson Mills	Rapids View	One of the last remaining old style pit toilets in the park system.	Flush restrooms available 800' away located at the trailhead. A 20 car lot makes it difficult to justify a restroom building. Trust Fund grant being pursued.	To be determined	2025	3
Dexter-Huron	East Dexter-Huron Comfort Station	Restrooms need accessibility improvements	Lavatory insulation, Door handles and closer needed.	To be determined	2025	3
Indian Springs	Meadowlark	Restrooms need accessibility improvements	Toilet needs moving, front approach to stall does not meet standard, door not self closing, stall width needs widening.	To be determined	2025	3
Huron Meadows	Cedar Ridge	Restrooms need accessibility improvements	Grab bar adjustment, stall door needs closer and door pull	To be determined	2025	3
Hudson Mills	Pine View	One of the last remaining old style pit toilets in the park system.	Consider eliminating / relocating this picnic area closer to the Activity Building.	To be determined	2025	3
Kensington	Equestrian Staging	Restroom building needed. Locate close to hike-bike trail.	Restroom will serve two user groups. Water needed for horses. None at this time.	To be determined	2025	3
Kensington	Possom Hollow	Restroom renovations needed.	Install tactile sign in proper location, remove front approach obstructions, concrete work to level threshold, insulation for pipes, adjust hand dryer, alter compartment for 60" clearance, install grab bars, move flush control,	To be determined	2025	3
Kensington	Playfield	One of the last remaining old style pit toilets in the park system.	Consider eliminating because of proximity to existing flush restrooms or relocate so facilities are spread out.	To be determined	2025	3
Kensington	East Boat Launch	One of the last remaining old style pit toilets in the park system. Consider replacing with a Pre-Fab Restroom Building. Access walks to existing restrooms may allow these to be removed.	Consider relocating shelter closer to restrooms and eliminating pit toilets.	To be determined	2025	3
Kensington	Boat Rental	Restroom renovations needed.	Women's front approach, coat hook and womens toilet partition, men's toilet compartment needs altering.	To be determined	2025	3

Kensington	Orchard Restroom	Restroom renovations needed.	Relocate signs, lower mirrors, alter compartment for 60" width in stalls, mens doe not have 12" clearance between grab bar and projecting object above, install rear grab bar, move flush control or reconfigure water closet. Remove obstructions to front approach.	To be determined	2025	3
Lake Erie	Cove Point	Restrooms need accessibility improvements	Sign needs to be mounted on latch side. Front approach entrance needs to meet maneuvering clearance. Insulate pipes. Grab bar relocation and space requirements if constructed before 2012. Move flush control. Add closer to stall door. Add door pulls if constructed after 2012.	To be determined	2025	3
Lake Erie	Boat Launch	Restrooms need accessibility improvements.	Relocate sign to meet standards, entrance door hardware replacement and adjust closer. Grab bar space requirements need relocating. Move flush control, along with stall door handles and closer added. 2018 MNTF Grant pursuit would include these improvements if awarded.	To be determined	2025	3
Lake St. Clair	Grill Restrooms	Restrooms need accessibility improvements. Access to building was recently improved. Accessible route >5%, mens stall door needs closer, door pulls on both sides, toilet paper dispenser too close	Closest restroom facility to the recently updated playground.	To be determined	2025	3
Oakwoods	Cedar Knoll	One of the last remaining old style pit toilets in the park system.	Little used picnic area.	To be determined	2025	3
Stony Creek	Trolley Trails	Restrooms needed. Consider a Pre-Fab Restroom Building.	Area has expanded as a winter use area and does not have restrooms.	To be determined	2025	3
Stony Creek	Inwood Trails	Restroom building needed.	Have discussed adding a prefab restroom building. No restrooms at this time.	To be determined	2025	3
Stony Creek	Shore Fishing	One of the last remaining old style pit toilets in the park system. Consider replacing with a Pre-Fab Restroom Building.	Consider replacing with porta-john based on use.	To be determined	2025	3
Delhi	Skips	Restroom building needed.	Something needs to be done at this heavily used facility.	To be determined	2027	4
Kensington	Mitten Bay	One of the last remaining old style pit toilets in the park system. Consider replacing with a Pre-Fab Restroom Building.	Consider improving facilities for boaters.	To be determined	2027	4
Kensington	Shore Fishing	One of the last remaining old style pit toilets in the park system. Consider replacing with a Pre-Fab Restroom.	Consider improving facilities for fisherman and those launching kayaks.	To be determined	2027	4
Lake Erie	Marina Building	Restrooms need accessibility improvements.	Signs need relocating and text revised, new door hardware and adjust closer, alter toilet room, insulate pipes, lower counter, move toilet, grab bar relocation, toilet paper dispenser relocate.	To be determined	2027	4
Lake Erie	Food Bar	Restrooms need accessibility improvements	Accessible route vertical threshold exceeds standard. Relocate sign. Womens does not meet clear floor space standard. Fix coat hook, move toilet and grab bar. Appears toilet dispensers need relocating and womans front approach to stall needs reconfiguring along with door pulls added. Both compartments need to be widened.	To be determined	2027	4

Hudson Mills	Disc Golf Course	One of the last remaining old style pit toilets in the park system.	Disc golf course is heavily used. Consider providing an accessible restroom with a pathway surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2029	5
Hudson Mills	Activity Center	Restrooms need accessibility improvements.	Difficult project. May need a new restroom building for the Activity Area.	To be determined	2029	5
Hudson Mills	Group Camp	Three restrooms currently located in the Group Camp.	Suggest locating one to the north where it is more rustic and where it can be used by Canoe Campers and Group Camp users.	To be determined	2029	5
Indian Springs	Golf Starter Building	Restrooms need accessibility improvements	Sign relocation, door knob replacement and closer, mens privacy wall, coat hooks, move toilet, grab bars	To be determined	2029	5
Kensington	Disc Golf Course	Restroom building needed.	Consider adding restrooms for Disc Golf Users. Course is being expanded to 36 holes and only has porta-johns.	To be determined	2029	5
Kensington	Group Camp	Five restrooms currently located in the Group Camp.	Consider replacing with one or two Pre-Fab Restroom Buildings. Consider locating one on the west side of the river that can be used by multiple sites.	To be determined	2029	5
Kensington	Park Office	Restrooms need accessibility improvements.	Does not meet clear floor space in bathroom. Coat hook needs adjusting. Mens lavatory does not meet clear floor space. Pipes need insulating. Soap dispenser needs adjusting. Water closet does not meet clearance width. Stall door width not met and door pulls.	To be determined	2029	5
Lake Erie	Golf Course	Restrooms need accessibility improvements	Relocate sign to meet standards. Toilet rooms do not meet clear floor space standard. Adjust soap dispenser, grab bar, and toilet roll dispenser. Add door pulls and womens stall door needs closer.	To be determined	2029	5
Lake St. Clair	North Marina	Restrooms / Shower Facilities need accessibility improvements.	Has another shower building as an option.	To be determined	2029	5
Huron Meadows	Golf Starter Building	Restroom renovations needed.	Sign needs to be mounted on latch side and lowered in height, front approach not in compliance, threshold exceeds limit, lavatory needs insulation, move toilet, grab bars, stall width needs widening.	To be determined	2029	5
Wolcott Mill	Camp Rotary	Restroom renovations needed.	Accessible route greater than 5% and less than 8%, follow ramp standards or re-grade. Lower signs, door closer, lower mirrors, coat hooks, stall front approach and width not in compliance.	To be determined	2029	5
Wolcott Mill	Camp Rotary Activity Center Restrooms	Restroom renovations needed.	Adjust closer, mens toilet and womens flush control relocated, womens stall widened, mens front approach does not meet 60" depth, door not self-closing, missing handle.	To be determined	2029	5

PRIORITY 4. SECONDARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Total Spaces	Total # of HC Spaces	# that are Van Accessible	Required HC Spaces	Required Van Spaces	Space Meet All Requirements	Notes/Solution	Cost	Timeline	Priority Ranking
Hudson Mills	Rapids View	30	2	1	2	1	Yes	Appears to meet requirements	Not available	Completed 2019	0
Indian Springs	Park Office	76	4	4	4	1	Yes	Appears to meet all requirements.	Not available	Completed 2018?	0
Kensington	Island Road North Lot	40	2	2	2	1	Yes	Appears to meet all requirements.	1,040	Completed 2019	0
Lake Erie	Park Office Visitor Lot	26	4	4	2	1	Yes	Appears to meet all the requirements	673	Completed 2019	0
Lower Huron	Elhwoods Roadside North	11	0	0	1	1	Yes	Group with the main Elhwoods North lot	539	Completed 2019	0
Lower Huron	Elhwoods Roadside South	10	0	0	1	1	Yes	Group with the main Elhwoods North lot	539	Completed 2019	0
Lower Huron	Group Camp North	79	2	1	3	1	Yes	Appears to meet all requirements	539	Completed 2019	0
Lower Huron	Group Camp Roadside Lot	20	0	0	1	1	Yes	Recommend grouping parking lot count with the south lot.	539	Completed 2019	0
Stony Creek	Park Office	27	2	1	2	1	Yes	Appears to meet all requirements.	700	Completed 2019	0
Willow	Indian Ridge	49	2	1	2	1	Yes	Appears to meet requirements	593	Completed 2019	0
Willow	Flintwoods West	40	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Flintwoods East	44	4	4	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Elder Creek South	66	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Elder Creek North	39	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Chestnut North	99	4	1	4	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Chestnut East	55	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Chestnut South	46	2	1	2	1	Yes	Appears to meet requirements	593	Completed 2019	0
Willow	Big Bend West	79	4	1	4	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Big Bend South	68	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Willow	Washago Pond South	100	5	1	4	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Wolcott Mill	Farm Center Service Yard	0	0	0	0	0	Yes	An accessible space may be required. Low priority.	Not available	Completed 2019	0
Dexter-Huron	Southwest Lot	38	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Lower Huron	South Fishing Site	23	1	1	1	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Kensington	Island Road South Lot	40	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Lower Huron	Elhwoods South	46	2	1	2	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Lower Huron	Walnut Grove Lot 3 South lot by restrooms	61	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Stony Creek	West Branch Roadside Lot	25	1	1	1	1	Yes	Appears to meet all requirements	593	Completed in 2019	0
Stony Creek	West Branch South Lot	57	3	1	3	1	Yes	Appears to meet all requirements	593	Completed 2019	0
Lower Huron	Par-3 Lot	79	4	1	4	1	Yes	Appears to meet all requirements	593	Completed in 2019	0
Wolcott Mill	Shorian Lodge	5	1	1	1	1	Yes	Appears to meet all requirements	593	Completed in 2019	0
Willow	Acorn Knoll South (gravel)	56	0	0	3	1	No	Recommend locating two spaces close to the restrooms and one near the hike-bike trail connector.	To be determined	2021	1
Kensington	General Motors Road Lot	18	0	0	1	1	No	An accessible space may be required. Low priority.	To be determined	2023	2
Lake Erie	Boat Launch Overflow (gravel)	29	0	0	2	1	No	Recommend adding two spaces for bird watchers that use the lot and for trail access.	To be determined	2023	2
Wolcott Mill	Camp Rotary Equestrian Staging (grass)	10	0	0	1	1	No	Not a parking lot	To be determined	2023	2
Wolcott Mill	North Branch Trails	121	6	2	5	1	Yes	Pavement is in poor condition	To be determined	2023	2
Delhi	West Delhi	28	2	1	2	1	Yes	Recommend locating close to the kayak launch. No striping, pavement very old gravelly	To be determined	2025	3
Kensington	Mitten Bay (gravel)	40	0	0	2	1	No	Accessible spaces needed. Recommend locating close to the access path to the boat slips and hike-bike trail. Low priority.	To be determined	2025	3
Kensington	Disc Golf (gravel)	48	0	0	2	1	No	Accessible spaces may be needed. Low priority. Locate accessible spaces closest to the starter booth.	To be determined	2027	4
Lower Huron	Group Camp South	57	4	1	3	1	Yes	When the three lots are grouped together 6 spaces are required. Recommend locating all 4 spaces close to the restroom building and creating one or two accessible sites. Additional striping and signs needed. Van sign needed.	To be determined	2027	4
Oakwoods	Equestrian Staging (gravel)	16	0	0	1	1	No	Accessible space needed. Low priority.	To be determined	2027	4

Oakwoods	Cedar Knoll West (gravel)	50	0	0	2	1	No	Accessible spaces needed. Redesign of the lot is being considered. Recommend grouping the parking totals from both lots and locating	To be determined	2027	4
Oakwoods	Cedar Knoll East	100	0	0	4	1	No	Accessible spaces needed. Recommend grouping the parking totals from both lots and locating all accessible spaces within the	To be determined	2027	4
Hudson Mills	Disc Golf	25	0	0	1	1	No	No lot	To be determined	2029	5
Hudson Mills	Group Camp Southwest Lot	20	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Hudson Mills	Group Camp Southeast Lot	25	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Hudson Mills	Group Camp Middle Lot	40	0	0	2	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Hudson Mills	Group Camp East Lot	19	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Hudson Mills	Group Camp North	20	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Hudson Mills	Fishing Site	20	0	0	1	1	No	Recommend adding a space close to the trail. Leave space as an aggregate parking space. Low priority.	To be determined	2029	5
Kensington	Flagstaff (gravel)	23	0	0	1	1	No	Accessible spaces may be needed. Recommend grouping parking totals with the Turtlehead Lot. These are parallel parking spaces on aggregate. No accessible facilities in the area.	To be determined	2029	5
Kensington	Playfield Roadside	34	0	0	2	1	No	Accessible parking spaces may be needed. Recommend grouping parking counts with the Possum Hollow.	To be determined	2029	5
Kensington	Route 3 Overlook Parking	24	0	0	1	1	No	Not a parking lot	To be determined	2029	5
Kensington	Overlook Parking (Office)	24	2	1	2	1	Yes	Appears to meet all requirements	To be determined	2029	5
Kensington	Mill Site (Dawson Road) gravel	10	0	0	1	1	No	An accessible space may be required. Low priority.	To be determined	2029	5
Kensington	Equestrian Staging	0	0	0	0	0	Yes	An accessible space may be required. No formal parking lot. Low priority.	To be determined	2029	5
Kensington	Group Camp	0	0	0	0	0	Yes	Accessible spaces may be required. No formal parking lots. Low priority.	To be determined	2029	5
Lake Erie	Marina Overflow Lot	98	0	0	4	1	No	Gravel lot is not appropriate for HC parking spaces. When grouped with all the other lots at the Marina there are a sufficient number of accessible parking spaces.	To be determined	2029	5
Lower Huron	Pool Service Yard	4	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5
Lower Huron	Walnut Grove Lot 2	64	0	0	3	1	No	Striping is not needed in this overflow camping lot.	To be determined	2029	5
Stony Creek	Oakgrove Roadside Lot	43	0	0	2	1	No	Recommend grouping parking counts with Oakgrove West. There are no amenities near this lot.	To be determined	2029	5
Stony Creek	Trolley Trails (gravel)	24	0	0	1	1	No	An accessible van space is needed. Low priority. Recommend leaving parking space unpaved.	To be determined	2029	5
Stony Creek	Inwood (gravel)	10	0	0	1	1	No	Accessible parking space needed. Low priority. Recommend leaving parking space unpaved.	To be determined	2029	5
Willow	Acorn Knoll North (disc golf)	50	0	0	2	1	No	Accessible parking spaces may be needed. Low priority.	To be determined	2029	5
Willow	Service Yard	0	0	0	0	0	Yes	Accessible parking spaces may be needed. Low priority.	To be determined	2029	5
Willow	Big Bend 2	25	1	0	1	1	No	Recommend grouping parking lot numbers with the south lot. There are no accessible facilities in the area.	To be determined	2029	5
Wolcott Mill	Model Airplane Field	23	0	0	1	1	No	An accessible space may be required. Low priority.	To be determined	2029	5
Oakwoods	Equestrian Staging	16	0	0	1	1	No	Accessible space needed. Low priority.	To be determined	2027	4
Lake St. Clair	Boat Launch	141	7	3	5	1	Yes	Appears to meet requirements	Not available	Completed	0
Lower Huron	Pool Service Yard	4	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2029	5

Kensington	Park Office	24	2	1	1	1	No	Signs appear to be installed too short. Striped van aisle needed. Van sign needed. Fix crumbled concrete at door threshold. Secure entrance carpet. Perm. Signs would need concrete cored	To be determined	2021	1
Kensington	Equestrian Staging	0	0	0	0	0	Yes	An accessible space may be required. No formal parking lot. Low priority.	To be determined	2029	5
Indian Springs	Prison Site	0	0	0	0	0	Yes	No designated parking spaces. Accessible spaces not required.	Not available	Completed	0
Lake St. Clair	Park Office	24	2	1	1	1	Yes	Appears to meet all requirements	Not available	Completed	0
Indian Springs	Park Office	76	4	4	4	1	Yes	Appears to meet all requirements.	Not available	Completed	0
Stony Creek	Park Office	27	2	1	2	1	Yes	Appears to meet all requirements.	Not available	Completed	0
Wolcott Mill	Camp Rotary Campfire. No lot.	17	1	1	1	1	Yes	An accessible route is needed to the campfire, recommend an additional space near campfire route.	To be determined	2029	5
Wolcott Mill	Camp Rotary Equestrian Staging. No lot.	10	0	0	1	1	No	An accessible parking space may be needed. Low priority. Turf lot.	To be determined	2029	5
Kensington	Canoe Camp/Livery	0	0	0	1	1	No	Suggest one ADA parking for van	To be determined	2027	4

PRIORITY 4. SECONDARY RECREATIONAL VISITOR APPROACH AND ENTRANCE AREAS

Park	Location	Description	Justification/Solution	Cost	Timeline	Priority Ranking
Hudson Mills	Disc Golf Course	Accessible route needed	Does not meet standards. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36" .	To be determined	2029	5
Kensington	General Motors Lot	Improved access desired from the lot to the hike-bike trail.	A more direct way to access the trail is desired.	To be determined	2027	1
Kensington	Group Camp Amphitheater	Accessible walks desired connecting a parking area, camp site, and the amphitheater.	Low priority.	To be determined	2029	2
Kensington	Windfall	Accessible walks desired connecting the parking lot, shelter, and restrooms.	Area is closed most of the time. Only use is when rented. Consider relocation of restrooms closer to the hike-bike trail for increased use. May want to remove facilities if the area is not opened to the public.	To be determined	2029	2
Kensington	Playfield Vault Latrines	Accessible walk desired to the women's restroom.	Men's has an access walk. Women's doesn't.	To be determined	2029	2
Kensington	Group Camp Sites	Accessible walks desired connecting the parking lot, restrooms, fire pit area, and accessible camp site.	Consider having one designated accessible camp site.	To be determined	2025	2
Kensington	Equestrian Staging Area	Accessible walk desired in front of the trailhead structure.	Low priority. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36" .	To be determined	2029	3
Kensington	Administrative Office	Improved ramp access desired.	1:10 slope flares required on ramps.	To be determined	2029	5
Kensington	Disc Golf Course	Accessible walks desired connecting the parking lot, starter building, porta johns, shelter, and kiosk structure.	No access paths to these facilities at this time. Access is not an issue if they are able to play disc golf.	To be determined	2029	5
Lake Erie	Basketball Court Access	Accessible walk desired connecting the Great Wave Activity Area to the basketball courts.	A paved path connects the lot to the basketball courts but does not provide access to accessible parking spaces or the Great Wave Activity Area.	5,740	2023	4
Lake St. Clair	Porta John Locations	Recommend locating porta johns on pavement or an aggregate surface that meets accessibility requirements.	Easily accomplished.	To be determined	2021	1
Lower Huron	Group Camp	Accessible walks desired connecting an accessible campsite, parking lot, restrooms, fire pit, and shelter.	Consider relocating the shelter to a location closer to the restrooms and parking to minimize lengthy walks.	To be determined	2029	2
Lower Huron	Group Camp Fountain	Accessible walk desired to the accessible drinking fountain.	Consider removing or relocating to a location along a path.	To be determined	2029	2
Lower Huron	Walnut Grove Playground	Accessible walk desired to the accessible playground. Recommend aligning the walk with the walk to the restrooms.	Difficult playground for the public to access unless you are a camper.	To be determined	2029	3
Lower Huron	Basketball Court Access	Accessible walk desired to the basketball courts. Access to the tennis court and basketball courts are in different locations. Recommend having access to both courts from the main walk.	Accessible basketball courts are located in other parts of the park. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36" .	To be determined	2029	4

Lower Huron	Tennis Court Access	Improved access to the tennis court is desired. Gate access is on the side opposite of the parking lot. A gate is needed to provide access between the basketball court and tennis court on the parking lot side of the court.	This is the only tennis court in the park. Court is deteriorating and has little use. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	Completed	4
Oakwoods	Equestrian Staging Area	Accessible walk desired to restrooms. Recommend installing pedestrian crossing signs at the road for access to the porta john or adding another porta john at the equestrian staging area. Recommend replacing the existing porta john with an accessible unit.	Access to restrooms is on the opposite side of the park road. The existing porta john is not an accessible unit and not located in an accessible location.	To be determined	2027	3
Wolcott Mill	North Branch Trails	Improve access desired to the trails. Parking bumpers block access at this time. Relocate porta johns and accessible parking spaces closer to the access point. Verify access points are wide enough and cross slopes at access point meet standards.	New projects should meet accessibility standards.	To be determined	2021	1
Wolcott Mill	Equestrian Staging Area	Accessible walk desired to and in front of the trailhead structure.	All trailheads should be located in accessible locations. Provide a surface that is firm and stable with a running slope no steeper than 5% and a cross slope not steeper than 2%, a minimum clear width of 36".	To be determined	2025	3

PRIORITY 5. NON-ESSENTIAL PARK USER RECREATIONAL SUPPORT, FACILITY SERVICES

Park	Location	Description	Justification/Solution	Cost	Timeline	Park Ranking2
Lake St. Clair	Porta John Locations	Recommend locating porta johns on pavement or an aggregate surface that meets accessibility requirements.	Easily accomplished.	To be determined	2029	2
Kensington	Park Office	Service counter, entrance mats	Does not meet standards. Provide a section of counter that is 28" to 36" and is at least 24" long in alterations. Provide a mat with a heavier backing or tape the mat to the floor.	To be determined	2029	5
Lake Erie	Office	Restrooms need accessibility improvements. Service counter exceeds counter height limit. Signs do not meet standards.	Remove obstructions to meet front approach maneuvering clearance, adjust door closers, relocate garbage cans obstructing clear path, adjust lavatory mirror and hooks, insulate pipes, move toilets and adjust stall widths to meet 60 inches. Grab bar relocations and flush control on open side. Front approach to stall does not meet maneuvering clearance.	To be determined	2029	5
Indian Springs	Office	Readjust door closer, secure carpet	Does not meet standards. Adjust the closer and provide a mat with a heavier backing or tape the mat to the floor.	To be determined	2029	5
Lake St. Clair	Park Office Parking Lot	Accessible walk desired from the employee parking lot to the park office. Ramp required.	Accessible spaces were recently removed from the lot when it was restriped. Ramped access desired at all employee entrances.	To be determined	2029	5
Lake St. Clair	Park Office	Ramp needed.	Provided a new curb ramp with a running slope no steeper than 8.3% and a cross slope no steeper than 2% and a smooth transition with 6' flares.	To be determined	2029	5
Stony Creek	Park Office	Improved ramp access desired. Reconstruct the ramp to meet current standards. 60" turning space required.	Park offices should be accessible. Provide a new ramp with a running slope no steeper than 8.3%, a cross slope no steeper than 2% and handrails on both sides that are mounted to 34" to 38" to the top of the gripping surface.	To be determined	2029	5
Kensington	Office	Service Counter	Does not meet standards. Provide a section of counter that is 28" to 36" and is at least 24" long in alterations.	To be determined	2029	5
Lower Huron	Office	Door hardware, closer adjustments, service counters	Does not meet standards. Door hardware and closer needs updating. Provide a section of counter that is 28" to 36" and is at least 24" long in alterations.	To be determined	2029	5
Lake St. Clair	Park Office Parking Lot	Accessible walk desired from the employee parking lot to the park office. Ramp required.	Accessible spaces were recently removed from the lot when it was restriped. Ramped access desired at all employee entrances.	To be determined	2029	5
Wolcott Mill	Model Airplane Field	Accessible walks desired connecting the parking lot, building, restrooms, a repair station, and a control station.	Facility maintained by another organization and not open to the general public.	To be determined	2029	5

PRIORITY 6. FACILITIES NEEDING FURTHER STUDY FOR FUTURE USE, RENOVATION, REPLACEMENT, OR REMOVAL

Park	Location	Description	Justification/Solution	Cost	Timeline	Park Ranking2
Wolcott Mill	Farm Center/Dairy Farm	Improved access desired to the small animal bar. Maintenance needed to remove tripping hazard.	A trip hazard exists preventing wheel chair access. Existing ramps need hand rails to meet standards. Replace inaccessible knobs. Note not part of this checklist, chicken coup is not accessible, horse barn and green house not accessible route or entrance. Existing aggregate paths may not meet accessibility standards. Master Plan for Farm Center under conceptual design, wait for preliminary design to implement ADA improvements.	To be determined	2021	1
Hudson Mills	Rapids View	Accessible walks desired to the vault latrines, hike-bike trail, and kayak launch.	Recommend waiting until there is a master plan for this area. Expanded parking, restrooms, and a drop off area for kayak unloading have been discussed.	To be determined	2021	1
Lake St. Clair	Boardwalk Shelter	Accessible walks desired connecting the boardwalk, shuttle stop, and future restroom building. Recommend waiting until there are plans made for the new restroom building.	No access at this time. Accessible restrooms needed.	To be determined	2023	2
Lake St. Clair	Creek View Shelter	Accessible walks desired connecting the boardwalk, shuttle stop, and future restroom building. Recommend waiting until there are plans made for the new restroom building.	No access at this time. Accessible restrooms needed.	To be determined	2023	2
Willow	Big Bend Restrooms	Accessible walk desired connecting the picnic shelter and restrooms. 470' of walk needed.	There are topography issues. Consider relocating the shelter in the future closer to existing restrooms.	To be determined	2023	2
Delhi	West Delhi	Access walks desired connecting the parking lot, restroom, and kayak launch.	The facility is very busy. The parking lot is in overflow regularly.	To be determined	2023	2
Wolcott Mill	Farm Center/Office	Main access routes	Running slope -7.3% treated as ramp for the concrete entrance to the Farm Center/Office.	To be determined	2023	2
Wolcott Mill	Farm Center	Improved surfacing desired to the upper shelter. Recommend paving a short segment of aggregate road leading o the upper picnic shelter. Ramp may be needed along route to park office.	Very short 20' segment, used heavily. Consider adding to the playground renovation project.	To be determined	2023	2
Stony Creek	Boat Rental	Restrooms need accessibility improvements. Entrance front approach standard and vertical threshold not met, door swing clearance and single user toilet room needs altering. Mirror exceeds height limit, insulation of pipes, towel dispenser exceed height max., various standards not met in bathroom stall.	Staff is currently presenting to Board various conceptual designs that include restroom improvements.	To be determined	2027	4
Wolcott Mill	Farm Center	Accessible walk desired to the spectating viewing area at the animal arena.	Access needed for this event area.	To be determined	2023	2
Wolcott Mill	Farm Center	Accessible walk desired connecting the Lower Shelter to the Farm Center / Restrooms.	Topography issues. Shelter is not rented that much. 410' of path needed.	To be determined	2023	2
Wolcott Mill	Farm Center	Accessible walk desired to the fishing dock.	Not used much. Consider grouping with the access walk project to the Lower Shelter. 185' of path needed.	To be determined	2023	2
Delhi	Skips Canoe Livery	General improvements needed to the area including accessible parking and walks to various buildings.	On the edge of the Natural Rivers Area. May require a permit for any type of work on, above, or below the ground.	To be determined	2027	4
Lake Erie	Marina Building	Goods and services accessibility improvements.	Interior doors do not meet threshold vertical height limit. Carpet is not secured along edges. Move garbage can from obstructing light switch. Service counter is higher than 36 inches.	To be determined	2029	5

PRIORITY 7. PHYSICAL STRUCTURAL BARRIERS IN FACILITIES THAT IMPEDE PARK EMPLOYEE BUT NOT GENERAL PUBLIC

Park	Location	Total Spaces	Total # of HC Spaces	# that are Van Accessible	Required HC Spaces	Required Van Spaces	Space Meet All Requirements	Notes/Solution	Cost	Timeline	Priority Ranking
Lake St. Clair	Nature Center Employee Lot	26	3	3	2	1	Yes	Appears to meet all requirements.	1,185	Completed 2019	0
Indian Springs	Prison Site	0	0	0	0	0	NA	No designated parking spaces. Accessible spaces not required.	Not available	Completed	0
Indian Springs	Golf Service Yard	0	0	0	0	0	NA	Accessible spaces may be needed. Low priority.	Not available	Completed	0
	West Branch South Lot	57	0	0	3	1	No	Three accessible spaces needed. Recommend grouping parking totals with the West Branch North West Lot and West Branch North East Lot.	To be determined	2027	4
Hudson Mills	Maintenance Yard 1	22	0	0	1	1	No	Accessible space may be needed. Low priority. An accessible ramp will be needed if added.	To be determined	2027	4
Lake Erie	Maintenance Yard	17	0	0	1	1	No	An accessible space may be required. Low priority.	To be determined	2027	4
Lake Erie	Golf Course Service Yard	0	0	0	1	1	No	An accessible space may be required.	To be determined	2027	4
Lower Huron	Maintenance Yard	8	0	0	1	1	No	May need an accessible parking space. Low priority.	To be determined	2027	4
Willow	Service Yard	0	0	0	0	0	NA	Accessible parking spaces may be needed. Low priority.	To be determined	2029	5
Hudson Mills	Maintenance Yard 2	0	0	0	0	0	NA	Accessible space may be needed. Low priority.	To be determined	2029	5
Lake St. Clair	Maintenance Yard	7	0	0	1	1	No	ADA spaces may be needed within facility. Plenty of areas to park if needed.	To be determined	2029	5
Hudson Mills	Golf Course Service Yard	0	0	0	0	0	NA	Accessible space may be needed. Low priority.	To be determined	2029	5
Huron Meadows	Golf Service Yard	0	0	0	0	0	NA	Accessible space may be needed. Low priority.	To be determined	2029	5
Huron Meadows	Engineering Office	5	0	0	1	1	No	Accessible space may be needed. Low priority.	To be determined	2029	5
Stony Creek	Golf Course Service Yard	0	0	0	0	0	Yes	An accessible space may be needed. Low priority. Currently parking on the sanitary tile field. A small staff parking lot is needed.	Not available	Completed 2019	0
Stony Creek	Service Yard	33	0	0	2	1	No	Accessible spaces may be needed. Low priority.	To be determined	2029	5
Kensington	Golf Service Yard	5	0	0	0	0	No	Accessible space may be needed. Low priority.	To be determined	2029	5
Wolcott Mill	History Center Employee Lot	10	1	1	1	1	Yes	Appears to meet all requirements. Consider signing a second accessible space if this parking area is open to the public and the area is used for event parking.	To be determined	2029	5
Lower Huron	Park Office and Employee Lots	38	1	0	2	1	No	The three lots combined require 2 spaces. One additional space needed. Striped van aisle needed. Van sign needed. Pavement is in terrible condition. New Park Office location proposed.	To be determined	2029	5
Lower Huron	Par-3 Maintenance Area	0	0	0	0	0	NA	May need an accessible parking space. Low priority.	To be determined	2029	5
Kensington	Park Office and Employee Lots										
Kensington	Maintenance Yard	81	0	0	4	1	No	Accessible spaces may be needed in multiple locations throughout the facility. Low priority.	To be determined	2029	5